


Steenbras: Site photographs



Temporary roadside reinforcement using sandbags and barriers to prevent further erosion of slope 1 along the Steenbras WTP access road



Natural water channel within the rocky terrain and dense fynbos vegetation within the proposed slope 1 rehabilitation area



Evidence of slope instability and erosion on slope 1 and views of the vegetation in the area (Kogelberg Sandstone Fynbos)



Temporary roadside reinforcement using sandbags and barriers to prevent erosion and support slope stability on the proposed rehabilitation area



Example of the blocked culvert and Kogelberg Sandstone Fynbos on the proposed slope 1 rehabilitation area



Dense Kogelberg Sandstone Fynbos vegetation in a mountainous landscape (proposed slope 1 rehabilitation area near the tar road). Natural water channel (encircled in yellow)



View of the Kogelberg Sandstone Fynbos and the damage to the slope 1 area